

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	6	("3827920").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:47
L2	4	("4013487").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:48
L3	2	("4568393").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:48
L4	2	("5653822").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:49
L5	2	("5792282").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:49
L6	2	("6093303").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:50
L7	2	("6149734").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:50
L8	2	("6413326").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:51
L9	2	("6458218").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:51

## EAST Search History

L10	2	("6461448").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:52
L11	2	("5702540").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:52
L12	2	("5000368").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:53
L13	2	("20060090817").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:54
L14	2	("6218642").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:54
L15	11	steel and nickel near plating and carburiz\$ and heat and remove and electroless	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:58
L16	38	steel and nickel and carburiz\$ and heat and remove and electroless	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 14:58